

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

### Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	10/19/2016 10/19/2016	Maksim Khashchuk

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD2085_01_s _ 2013_7				
Comment Code					
Inspector Comment					
The O&M Manual is available at the office.					

No Photos

LM Start		Rating **	A	Issue No.	9
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD2085_01_s _ 2013_9				
Comment Code					
Inspector Comment					
Flood fighting supplies are available at the River Club.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

### Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	10/19/2016 10/19/2016	Maksim Khashchuk

LM Start		Rating **	A	Issue No.	14	
LM End		Issue Type +	Ma	Location *	N/A	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Flood Preparedness & Training				°	
					°	
DWR ID	DWR_RD2085_01_s_2013_14					
Comment Code						
Inspector Comment						
The LMA has a flood fighting plan and training.						

No Photos

LM Start	0.12	Rating **	A/W	Issue No.	19
LM End	0.47	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			37.719052 °	37.723246 °
				-121.302928 °	-121.299492 °
DWR ID	DWR_RD2085_01_f_2015_19				
Comment Code					
C1 : Add appropriate material and re-grade the levee to bring the crown above the design elevation.					
Inspector Comment					
Disking on the levee shoulder. Make sure the water drains evenly to the slopes.					

Photo 1 of 1 : FA\_2016\_RD2085\_113\_19\_20160914\_00007.jpg



View of the disking on the levee crown shoulder.

LM Start	1.79	Rating **	M	Issue No.	39
LM End	1.79	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.711456 °	37.711456 °
				-121.282397 °	-121.282397 °
DWR ID	DWR_RD2085_01_s_2016_39				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
LMA has bait stations on the levee.					

Photo 1 of 1 : FA\_2016\_RD2085\_113\_39\_20160914\_00016.jpg



View of the rodent burrows on the landside levee slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

### Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	10/19/2016 10/19/2016	Maksim Khashchuk

Photo 1 of 3 : SJR2016\_RD2085U01RM66.5\_1.jpg



Close view of the erosion.

07/08/2016: No significant change observed.

09/10/2015: No significant change observed. Signs of animal activity are present.

09/10/2014: No significant change observed.

09/20/2013: No significant change in erosion observed. More vegetation at the site.

12/04/2012: The erosion has progressed remarkably toward levee, extended to the up-and downstream of the original pocket erosion. Trees and dense bush are present at the site. Animal burrow holes are visible, and possibly can cause seepage.

09/22/2010: No significant change observed. There is little visibility due to seasonal grass on the berm and slope.

08/18/2009: Site is located on berm; pocket erosion has developed; the site is covered in dense vegetation; there are several relief wells on the landside of the levee; site is Not Rated because berm width is greater than 30 feet; site should be monitored to keep track of erosion progress. [2016 Site ID:RD2085U01RM66.5]

Photo 2 of 3 : SJR2016\_RD2085U01RM66.5\_3.jpg



Direct view of the erosion. Note the dense vegetation at the site.

* Location	** Rating	+ Issue Type
LS : Land Side    N/A : Not Applicable	A : Acceptable                      N : Not Inspected/Rated	Ma : Maintenance Deficiency
WS : Water Side	M : Minimally Acceptable            C : Corrected	Ob : Design & System Obsolescence
CR : Crown	U : Unacceptable                      A/W : Acceptable but Monitor & Maintain	En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

### Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	10/19/2016 10/19/2016	Maksim Khashchuk

LM Start	<b>2.96</b>	Rating **	C	Issue No.	<b>41</b>
LM End	<b>2.96</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.698050°	37.698050°
				-121.277842°	-121.277842°
DWR ID	DWR_RD2085_01_s_2016_41				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	<b>3.03</b>	Rating **	C	Issue No.	<b>24</b>
LM End	<b>3.03</b>	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.697115°	37.697115°
				-121.277870°	-121.277870°
DWR ID	DWR_RD2085_01_f_2015_24				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	<b>3.34</b>	Rating **	N	Issue No.	<b>30</b>
LM End	<b>3.34</b>	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.693019°	37.693019°
				-121.277892°	-121.277892°
DWR ID	DWR_RD2085_01_s_2014_30				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---



# Reclamation District No. 2085 Kasson

No Photos

No Photos

Page 6 of 13

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

### Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	10/19/2016 10/19/2016	Maksim Khashchuk

LM Start	3.57	Rating **	M	Issue No.	45
LM End	3.57	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.690161 °	37.690161 °
				-121.276543 °	-121.276543 °
DWR ID	DWR_RD2085_01_s_2016_45				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 2 : FA\_2016\_RD2085\_113\_45\_20161024\_00050.jpg



View of the rodent burrows on the landside levee slope. Fall 2016

LM Start	<b>3.57</b>	Rating **	M	Issue No.	<b>45 (cont)</b>
LM End	<b>3.57</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : FA\_2016\_RD2085\_113\_45\_20160914\_00018.jpg



View of the rodent burrows on the landside levee slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

### Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	10/19/2016 10/19/2016	Maksim Khashchuk

LM Start	3.62	Rating **	A/W	Issue No.	2
LM End	3.75	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR Erosion Survey			37.688545 °	37.688545 °
				-121.276298 °	-121.276298 °
DWR ID					

**Comment Code**

**Inspector Comment**

07/08/2016: The erosion in the berm was found slightly progressed toward the levee toe. Signs of fresh erosion at the site are visible.  
 08/19/2015: No significant change observed.  
 07/17/2014: No significant change observed.  
 09/10/2013: No significant change observed.  
 12/04/2012: This site has been documented before, and a cost estimate to repair has been prepared dated 05/09/2010. The fresh cut shows the erosion is developing. The berm width is at least 42 feet. Sticks were placed at three locations along the river bank, with 3 sticks 5 feet apart at each location. [2016 Site ID:RD2085U01RM67.7]

LM Start	<b>3.62</b>	Rating **	A/W	Issue No.	<b>2 (cont)</b>
LM End	<b>3.75</b>	Issue Type +	Ma	Location *	WS

Photo 1 of 3 : SJR2016\_RD2085U01RM67.7\_1.jpg



View of the downstream end of the erosion.

Photo 2 of 3 : SJR2016\_RD2085U01RM67.7\_2.jpg



Close view of the erosion.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	10/19/2016 10/19/2016	Maksim Khashchuk

Photo 3 of 3 : SJR2016\_RD2085U01RM67.7\_4.jpg



Close view of the erosion.

LM Start	3.65	Rating **	M	Issue No.	37
LM End	3.65	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.689090 °	37.689090 °
				-121.276326 °	-121.276326 °
DWR ID	DWR_RD2085_01_f _ 2016_37				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

### Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	10/19/2016 10/19/2016	Maksim Khashchuk

LM Start	3.71	Rating **	A/W	Issue No.	25
LM End	3.71	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.688216 °	37.688216 °
				-121.276603 °	-121.276603 °
DWR ID	DWR_RD2085_01_f_2015_25				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Control levee access to prevent damage to levee slopes by vehicle.					

Photo 1 of 1 : FA\_2016\_RD2085\_113\_25\_20160914\_00009.jpg



View of the waterside levee slope damaged by vehicle.

LM Start	3.74	Rating **	A/W	Issue No.	26
LM End	3.74	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.687841 °	37.687841 °
				-121.276678 °	-121.276678 °
DWR ID	DWR_RD2085_01_f_2015_26				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					
Area should be maintained to prevent further levee damage.					

Photo 1 of 1 : FA\_2016\_RD2085\_113\_26\_20161024\_00049.jpg



View of the foot path on the levee slope.

LM Start	3.78	Rating **	M	Issue No.	46
LM End	3.78	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.687253 °	37.687253 °
				-121.276780 °	-121.276780 °
DWR ID	DWR_RD2085_01_s_2016_46				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

No Photos

* Location LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

### Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	10/19/2016 10/19/2016	Maksim Khashchuk

LM Start	3.86	Rating **	M	Issue No.	36
LM End	3.91	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.686059 °	37.685340 °
				-121.276745 °	-121.276594 °
DWR ID	DWR_RD2085_01_f_2016_36				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : FA\_2016\_RD2085\_113\_36\_20161024\_00048.jpg



View of the rodent holes on the levee slope.

LM Start	4.15	Rating **	M	Issue No.	34
LM End	4.15	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.682495 °	37.682495 °
				-121.274169 °	-121.274169 °
DWR ID	DWR_RD2085_01_f_2016_34				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : FA\_2016\_RD2085\_113\_34\_20161024\_00047.jpg



View of the rodent holes on the levee slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable  N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---





**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

### Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 San Joaquin River	Left	5.29	10/19/2016 10/19/2016	Maksim Khashchuk

LM Start	5.20	Rating **	M	Issue No.	52
LM End	5.20	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.675620 °	37.675620 °
				-121.269359 °	-121.269359 °
DWR ID	DWR_RD2085_01_s_2016_52				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : FA\_2016\_RD2085\_113\_52\_20161024\_00044.jpg



View of the tire tracks on the levee slope.

LM Start	5.24	Rating **	N	Issue No.	29
LM End	5.24	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			37.675099 °	37.675099 °
				-121.269264 °	-121.269264 °
DWR ID	DWR_RD2085_01_f_2015_29				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : FA\_2016\_RD2085\_113\_29\_20161024\_00043.jpg



View of the tree stump.

**\* Location**

LS : Land Side    N/A : Not Applicable  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable                      N : Not Inspected/Rated  
M : Minimally Acceptable        C : Corrected  
U : Unacceptable                  A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016**

**Reclamation District No. 2085 Kasson**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 San Joaquin River		0.70	10/19/2016 10/19/2016	Maksim Khashchuk

LM Start	0.02	Rating **	A	Issue No.	1
LM End	0.69	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.705041 °	37.714004 °
				-121.274570 °	-121.269690 °
DWR ID	DWR_RD2085_02_f _ 2016_1				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
LMA has good vegetation control this season.					

Photo 1 of 1 : FA\_2016\_RD2085\_114\_1\_20161024\_00001.jpg



View of the well maintained vegetation on the levee slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

### Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 San Joaquin River		0.29	10/19/2016 10/19/2016	Maksim Khashchuk

LM Start	0.01	Rating **	A	Issue No.	4
LM End	0.01	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			37.680574 °	37.680574 °
				-121.264585 °	-121.264585 °
DWR ID	DWR_RD2085_03_f_2016_4				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
LMA did a great job controlling the vegetation this season.					

Photo 1 of 1 : FA\_2016\_RD2085\_115\_4\_20161024\_00002.jpg



View of the well maintained vegetation on the levee slope.

LM Start	0.21	Rating **	U	Issue No.	1
LM End	0.23	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			37.682798 °	37.683052 °
				-121.262059 °	-121.261851 °
DWR ID	DWR_RD2085_03_s_2014_1				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Erosion of the waterside levee slope has been observed. The erosion is about 3 feet tall vertical from the slope to the base of projected levee toe.					

Photo 1 of 2 : FA\_2016\_RD2085\_115\_1\_20161024\_00003.jpg



View of the erosion at the waterside levee toe. Fall 2016.

LM Start	<b>0.21</b>	Rating **	U	Issue No.	<b>1 (cont)</b>
LM End	<b>0.23</b>	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : FA\_2016\_RD2085\_115\_1\_20160914\_00001.jpg



View of the erosion at the waterside levee toe.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

### Reclamation District No. 2085 Kasson

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 San Joaquin River		0.29	10/19/2016 10/19/2016	Maksim Khashchuk

LM Start	0.22	Rating **	C	Issue No.	6
LM End	0.22	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			37.682844 °	37.682844 °
				-121.262002 °	-121.262002 °
DWR ID	DWR_RD2085_03_f_2015_6				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	0.25	Rating **	M	Issue No.	7
LM End	0.25	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			37.683274 °	37.683274 °
				-121.261839 °	-121.261839 °
DWR ID	DWR_RD2085_03_f_2016_7				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : FA\_2016\_RD2085\_115\_7\_20161024\_00004.jpg



View of the tire tracks on the levee slope.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---